



SOLUTIONS FOR THE BUILT WORLD

# JFK Causeway



[www.wje.com](http://www.wje.com)

**WJE** | ENGINEERS  
ARCHITECTS  
MATERIALS SCIENTISTS

Wiss, Janney, Elstner Associates, Inc.

Brian D. Merrill, PE

# Brian D. Merrill, PE



Principal at WJE, 2013 – present

TxDOT: 1986 – 2013

State Bridge Construction &

Maintenance Engineer: 2000-2013

ASBI member since 2000

*“ASBI has met the standards and requirements of the Registered Continuing Education Program. Credit earned on completion of this program will be reported to RCEP at RCEP.net. A certificate of completion will be issued to each participant. As such, it does not include content that may be deemed or construed to be an approval or endorsement by the RCEP.”*



# Purpose and Learning Objectives

## **Purpose**

This presentation provides an educational forum that will focus on a few of the latest innovations and technologies in the construction industry.

At the end of this presentation you will be able to:

Understand the design and construction history of the bridge

Understand the service life implications of the assessment findings

Utilize lessons learned from this project to improve future designs

---


# Presentation Outline

- Bridge History
- Design Challenges
- Construction Challenges/Issues
- Condition Assessment Findings
- Service Life Discussion
- Lessons Learned



1930's Causeway

# Bridge History




# Bridge History

- Original 2-lane toll road built 1950
  - Only bridge crossing to Mustang Is.
  - Had two swing barges across channels
- New 4-lane roadway opened in 1973
  - \$2.5M
  - 83ft above the GIWW
  - **1<sup>st</sup> Precast Segmental Bridge in US**





# Bridge History



1950 Causeway



# Bridge History

- Designed by the University of Texas: Dr. John E. Breen, PhD, PE
- TxDOT Designer: Alan B. Matejowsky, PE (1944 – 2013)
- Designed based on 1/6 scale model
  - Creep/shrinkage effects
- Construction proof of concept
  - Meetings with contractors at lab
- Discussions with Jean Mueller




# Bridge History

## Research Reports (<https://ctr.utexas.edu/library/reports/>)

- Long Span Prestressed Concrete Bridges of Segmental Construction: State of the Art (0-121-1, 1969)
- Epoxy Resins for Jointing Segmentally Constructed Prestressed Concrete Bridges (0-121-2, 1974)
- The Design and Optimization of Segmentally Precast Prestressed Box Girder Bridges (0-121-3, 1975)
- Computer Analysis of Segmentally Erected Precast Prestressed Box Girder Bridges (0-121-4, 1974)
- Construction and Load Tests of a Segmental Precast Box Girder Bridge Model (0-121-5, 1975)
- **Minimizing Construction Problems in Segmentally Precast Box Girder Bridges (0-121-6F, 1975)**


# Design Challenges

- AASHTO/US Industry Guidance missing or insufficient for:
- PT anchor zones
- Friction/wobble coefficients
- Epoxy joining of segments
- Geometry control
- Creep/Shrinkage
- No design software




# Design Aspects


1. Full segment out of balance
2. Temporary connections to piers: Tie downs
3. Load balancing with simple neoprene bearings
4. Grouted within 48 hours of stressing



# Design Aspects




# Design Aspects: "Simplicity"






# Design Details




# Design Details




Half Elevation : Tendons

# Design Details




# Design Details

## Cantilever Tendons




## Continuity Tendons



# Design Details

## Single Large Shear Key



# Construction Challenges

- Balanced cantilever – full segment out of balance
- Segment Delivery/Erection
- Epoxy application
- Duct alignment/“pullout”
- Segment cracking





# Construction Challenges


- Balanced cantilever – full segment out of balance
- Temporary hold-down bars (not Post Tensioned)
- Nuts periodically loosened



# Construction Challenges

Segment Delivery: 1 Barge Mounted Crane + Custom Hardware

Epoxy applied to both faces  
before lifting segments



# Construction Challenges

## Duct Alignment

- Used thin-walled metal ducts
- Insufficient attachment to rebar
- No inflatable alignment tubes
  - High friction values
  - Replace several tendons due to installation trouble
  - Tendon blockage/duct pullout



# Construction Challenges

- Web cracking at cantilever tendons
- All 88 segments cast when discovered
- Project shut down 9 months for study

Cracking caused by:

- Anchorage geometry changes
- Insufficient local zone reinf.
- Other rebar cut for tendons
- **Did not affect capacity – epoxy seal**



# Condition Assessment – Scope

- Review Plans/Reports
- Visual inspection of 100% of interior/exterior
- Locate PT/anomalies using NDE: GPR, IE, UST
- Inspect grout and tendon conditions
- Sample grout



# Condition Assessment – Scope


- Service Life Modeling
  - Cores for chloride testing/petro
  - Clear cover survey – GPR
  - Half-cell corrosion potential – selected locations
  - Corrosion rate – selected locations
- Goal: 30 Year Extension





# PT Assessment

- Statistical approach per FHWA-HRT-13-028
- Pre-selected locations  
(not random – limited to outside lanes)
- 75% Confidence level per TxDOT
  - 6 Cantilever tendons
  - 6 continuity tendons: deck anchors + interior locations
  - Borescope + Invasive openings  
(all were internal tendons)



# Assessment Findings – PT System

- Only one anomaly type
- Two grout voids found
- Strands were in like no
- Evidence of regrouting
- Pictures...



# Visual Assessment Findings

## Exterior:

- Cracking in web (epoxy seals intact, cracks)
- Spalling of end top
- Corrosion/spalling
  - Pictures...





# Visual Assessment Findings

## Interior

- Diaphragm cracking
- Web cracking
- Moisture at deck anchor
- **No Joint Leakage**




# Service Life Results



Coring Locations – 16 cores

# Chloride profiles - Webs




Exterior Face

Facing prevailing winds

Interior Face

# Chloride profiles – Top slab

Top - Under Asphalt




Wing Underside



# Chloride profiles – Approach Slabs


Top

Underside




Top

Underside




# Service Life Considerations

- Design Clear Cover:  
1" top slab/wings  
1.5" for webs and  
bottom slab
- Black Rebar
- Std. Concrete mix
- No external coatings



ASSESSMENT LOCATION OVERVIEW




HCP DATA CONTOUR PLOT

# Service Life Considerations

## Exposure Zones/Cases:

1. Deck surface in EB lanes:  
better overlay w/ membrane
  2. Deck surface for WB lanes:  
older overlay, no membrane
  3. Underside of wings
  4. Webs/bottom slab
- Clear cover to rebar matched plan dimensions
  - “extra” steel installed did not often match clear covers
  - Wind direction affected chloride exposure
  - ACP Overlay protects deck

# Service Life Results




# Rehabilitation Recommendations

- Replace overlays using membrane or use Polyester Polymer Concrete (PPC)
- Replace expansion joints
- Spot repairs to isolated spalling/cracking
- Water-repellant coating to exposed exterior surfaces
- Replace end tendon anchor pour-backs
- Possible cathodic protection system to piers

# Lessons Learned

## Research Report 6

- Improved anchor zone reinf. provisions (mock-ups)
- Increase element dimensions (slabs/webs) to improve constructability – but adds weight
- Needed better moment connection at piers
- Locate tendon anchors outside the webs (blisters)
- Robust ducts
- Multiple, Castellated shear keys better



# Lessons Learned – Assessment Findings

- No substitute for clear cover
- Protect end anchors near expansion joints
- Epoxy – both faces
- Pay attention to grouting (they did)
- QC for segment production
- Tendon anchors in deck could cause problems








SOLUTIONS FOR THE BUILT WORLD

# JFK Causeway

This concludes the educational content of this activity



[www.wje.com](http://www.wje.com)

**WJE** | ENGINEERS  
ARCHITECTS  
MATERIALS SCIENTISTS

Wiss, Janney, Elstner Associates, Inc.

Brian D. Merrill, PE